

Key to Minerals Map



South Lanarkshire Boundary



Construction Aggregates
(rock, sand and gravel)



Coal and Fireclay



Settlement Boundary



'A' Class Road



Major 'B' Class Road



Motorway



Ethylene Pipeline Hazard Zone



High Pressure Gas
Pipeline Hazard Zone



Bings Existing

- 1 Newton
- 2 Loanend/Spittal
- 3 Craignowe - Blantyre
- 4 Calderdale/Auchentibber
- 5 Auchentibber/Parkneuk
- 6 Udston
- 7 Quarter
- 8 Mid Quarter
- 9 Merryton
- 10 Millburn
- 11 Overwood
- 12 Lochhead/Broomfield
- 13 Law - Shawgill
- 14 Carluke - Castlehill
- 15 Kilincadzow - Leemuir
- 16 Kilincadzow - Gateside
- 17 Kilincadzow - Drums
- 18 Haywood
- 19 Tarbrax
- 20 Douglas Water



Ravenstruther Rail Terminal



Mineral Sites

- 1 Edge Farm
- 2 Carscallan
- 3 Ross Tip
- 4 Rigg Farm
- 5 Cladance Moss
- 6 Snabe
- 7 Bankend
- 8 Dunduff
- 9 Wilsontown
- 10 Hardgatehead
- 11 Garvald
- 12 Newbigging
- 13 Woodend Farm
- 14 Ryeflat Moss
- 15 White Loch and West End Wood
- 16 West End Wood
- 17 Hyndford
- 18 Prettsmill
- 19 Cloburn
- 20 Annieston Farm
- 21 Hillhouse
- 22 Broken Cross (in aftercare)
- 23 Mainshill (in aftercare)
- 24 Glentaggart (in aftercare)
- 25 Thirstone
- 26 Duneaton



Bings Reclamation

- 1 Cadzow
- 2 Auchlochach No.9
- 3 Bellfield